

# *COVER PLATE*

Material:- Hot rolled and pickled Low Carbon strip. Originally, this component was being treated by a competitive Salt bath treatment, unfortunately, this type of treatment left some form of contamination and at worst, a black deposit, which had to be removed by the customer using a post treatment cleaning cycle. Nitrotec was chosen because it was cost effective, giving a deeper, more consistent iron nitride layer with improved cleanliness removing the need for a post cleaning operation.

